


NOTE: RWPs 1, 3, 6 & 9 NOT SURVEYED DUE TO DEPOSIT LEVELS



KEY

	PROPOSED NEW DRAINAGE
	LENGTH OF PIPE TO BE REPAIRED/REPLACED
	NEW RODDING EYE
	PROPRIETARY PIPE LINING PROPOSED